

INFORMATION REPORT INFORMATION REPORT

CENTRAL INTELLIGENCE AGENCY

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

S-E-C-R-E-T

25X1

COUNTRY USSR/East Germany

REPORT

SUBJECT Soviet Naval Vessels Observed in the Baltic Area

DATE DISTR. 19 December 1958

NO. PAGES 1

REFERENCES

25X1

DATE OF INFO.

PLACE & DATE ACQ.

SOURCE EVALUATIONS ARE DEFINITIVE. APPRAISAL OF CONTENT IS TENTATIVE.

25X1

Att.No.

Vessels

1

In Kronshtadt: Three submarines
four cruisers
SVERDLOV-class, one under
construction, and the ADMIRAL MAKAROV; two
destroyers and auxiliaries
In Riga: One M-class
submarine and submarine class unidentified.

25X1

25X1

2

KRONSHADT-class submarine chaser
off Tallinn. Large naval vessel
/KIROV-class/ and two destroyers with
scaffolding around the foremasts in
Kronshtadt. KRONSHADT-class submarine
chasers in Sassnitz.

25X1

25X1

3

Sighting of the EKVATOR, NARA, KRONSHADT-
class submarine chaser submarine
(in Riga)

25X1

4

Two unidentified naval vessels at the
fitting-out basin in Zhdanov Shipyard,
Leningrad, with scaffoldings around the
foremasts. No description.

25X1

S-E-C-R-E-T

25X1

STATE	X	ARMY	X	NAVY	#X	AIR	X	FBI		AEC									
-------	---	------	---	------	----	-----	---	-----	--	-----	--	--	--	--	--	--	--	--	--

(Note: Washington distribution indicated by "X"; Field distribution by "#".)

INFORMATION REPORT INFORMATION REPORT

[REDACTED] two naval vessels lay at the fitting-out basin of
the Sydanov Shipyard in Leningrad. Scaffoldings were erected around
the vessels' foremasts.

25X1

~~SECRET~~

25X1

DISTRIBUTION

SECRET

att. No. 1

The following observations were made


25X1

- Seen in Kronstadt were cruiser [redacted] of the SVERBLOV class and another one, a ship similar to the PROVORNYI class destroyers [redacted] a number of minesweepers and a large icebreaker.

25X1

- Observed in Riga were a submarine of the "M" class and approximately six small patrol vessels. In Riga bight was submarine [redacted] (see sketch)

25X1

 An exhaust pipe on each side for gases from two diesel motors.

In Kronstadt were the armored ship [redacted] (on its way out to sea), the cruiser ADMIRAL MAKAROV at anchor in the roadstead, a frigate and a submarine underway in the roadstead, and a cruiser under construction.

25X1

S-E-C-R-E-T

25X1

DISTRIBUTION

SECRET

1. The KRONSTADT class subchaser [redacted] was observed at the buoy off of Tallin. [redacted]

2. The following were seen in Kronstadt:

- a. A large naval vessel [redacted]
- b. Two destroyers with scaffolding around the foremast.
- c. [redacted]

3. Patrol Boat [redacted] was observed off of the entrance to Riga [redacted]

4. Subchaser [redacted] and one other, of the KRONSTADT class, were observed in Sassnitz.

5. KRONSTADT class Subchasers [redacted] were seen in Sassnitz.


6. KRONSTADT class Subchasers [redacted] were seen in Sassnitz. [redacted] departed [redacted]

S-E-C-R-E-T

DISTRIBUTION

The following observations were made on the dates indicated:

- In Riga there were a small number of motor torpedo boats lying in the harbor, at [redacted]
- Outside Hälsingborg, Sweden, the school vessel EKVATOR was sighted northbound at a speed of 14 knots.
- The tanker NARA outside Hälsingborg, Sweden, sighted [redacted] northbound in a loaded condition, at a speed of 10 knots.
- In a canal south of Winterhafen in Riga were observed about forty motor torpedo boats and submarine [redacted] (see sketch)



Outside Kronstadt were seen two cruisers, ten odd minesweepers, and three submarines. In Kronstadt were twenty-odd destroyer-like vessels.

t - In Sassnitz was the KRONSTADT class submarine chaser [redacted] with three others.

[redacted] - In Riga Bight were seen a large number of submarines which practiced torpedo firing at a small zig-zagging warship.

S-E-C-R-E-T

DISTRIBUTION